



SHOWN LOGO PLATE (BOTTOM / RIGHT POSITION) SHOULD BE DISASSEMBLED. PLEASE KEEP SCREWS FOR FURTHER USE.








OVERLAY TOUCH KIT
SHOULD BE PUT ON
SMOOTH SURFACE (ETC.
CUSHION). CABLE
DIRECTION SHOULD BE
ON BACK.









TV PRODUCT SHOULD BE PUT ON OVERLAY TOUCH KIT CAREFULLY.










SCREW M4X16 3 PCS


(TORQUE: 0,9Nm ±%20)



OVERLAY KIT SHOULD BE ASSEMBLED BY METRIC-4 SCREWS TO ONLY "M" MARKED HOLES ON PLASTIC PARTS.









USE CABLE HOLDERS FOR CABLE POSITIONING.










SCREW M4 1 PCS

(TORQUE: 0,9Nm ±%20)



PLEASE ASSEMBLE LOGO PLATE.



